

①

Old Shell Station File Review, 10/24/97 mark

— Notice of Intent to close tanks, 3/20/90

• Tankowner, Fern Pike

P.O. Box 765 / 709 E. Harden St.

Graham, NC 27253

(910) 228-1300

site, Old Shell Station

709 E. Harden St.

Graham, NC 27253 (910) 226-6455

• tanks to be removed, 4K Gas

4K Gas

4K Gas

4K Gas

550 g. #2 Fuel Oil

^{proposed} consultant, Piedmont Environmental Services, Inc.

contact - Bill Stewart (910) 668-4821

— Closure Report, 7/14/97

• actual consultant used, Ecological Services, Inc.

contact - Diana Lanier (704) 399-4000

• new site name, European Auto Repair

• On 3/90 4 gas UST's were removed by Mr. A.M.

Perry with J.W. Long Sand & Grading @ 1202 Rahnott St., Burlington, NC 27205; (910) 227-4244.

• Soil samples were collected on 6/24 & 6/25/97

• UST's were in operation from 1964 to 10/89.

• Surroundings - residential/commercial

• A small creek is found to the Northeast

• Groundwater flow is to the East.

• Surroundings are served by public H₂O & sewer.

• Residuals from each UST removed on 3/29 & 3/30/97

- Contradictory: consultant says "storage & sampling of residual ~~material~~^{val} material in the VSTs couldn't be determined" ???
 supposedly the residuals were disposed of by Safeway Tank Disposal.

- Excavation included:
 - ① Removal of VSTs
 - ② On-site stockpiling of excavated soil.
 - ③ Refilling of the excavation w/ stockpiled soil.

- Dimensions of excavation: 42 x 11 x 35

- No Groundwater in excavation.

- ^{Top of} VSTs were located 2' BGL.

- The bottom of the excavation was @ 11'

- No soil was removed from the site.

- 300 tons of backfill was also used to fill the excavation.

- ESI utilized a geoprobe to collect soil samples. Auger/probe refusal occurred @ 12'. Thus, three sample points were chosen @ 12'.

- 5 soil samples were collected & analyzed via 5030

- According to Mr. Perry refusal @ 12' is likely due to filling of the excavation in '90 w/ broken concrete.

- samples taken on 6/24 & 6/25/97.

- A Groundwater sample was attempted to be acquired, but refusal consistently occurred btwn. 10' & 12'.

- Soil sample results:

6/24 { GA-1 (0'-4') —
 GA-2 (4'-8') —
 GA-3 (8'-10') —

6/25 { GB-1 (9'-13') —
 GB-2 (8'-11') —

to the east

②

• Attachments:

- ① USES Map
- ② Site Map
- ③ Certificate of Tank & Residual Disposal
- ④ C-O-C
- ⑤ Lab Results

